



Underwriters Laboratories Inc.®

12 Laboratory Drive
P.O. Box 13995
Research Triangle Park
North Carolina 27709-3995
(919) 549-1400
FAX No. (919) 549-1842

February 8 1996

(813) 593-0652



Clearwater Enviro Technologies, Inc.
12912 126th Terrace N.
Largo, Fl. 34644
Attention: Mr. Jeffrey M. Conway

Reference: 96RT01325

Subject: Sanitation Evaluation of Copper/Silver Ion Generator

Dear Jeff:

The following will report the results of the Sanitation evaluation of the copper/silver ion generator.

The copper/silver ion generator is made up of the following components.

- Control box - Manufacturer, Carlon model NR864
- Flow cell - Manufacturer, Spears 2 in. tee.
- Set of electrodes - Manufacturer, 3 J Machinery Co. model CLE-02
- Copper level test Kit - Manufacturer, Lamotte Chemical EC-70

Scientific evidence has been provided to Underwriters Labs Inc. A review of this evidence to NSF Standard 50 indicates that the above equipment is effective for supplemental treatment of water in swimming pools when used in conjunctions with not less than 0.4 ppm free chlorine.

It should be noted that additional chlorine may be required by the local health authority in accordance with local codes.

If you have any questions, please contact the undersigned

Sincerely,

Carl C. Radcliffe
CARL C. RADCLIFFE
Engineering Group Leader
Engineering Services
Ph (919) 549-1678
Fax (919) 547-6028

Reviewed By

Dan Chudy
DAN CHUDY
Engineering Group Leader
Engineering Services